

General Environmental Incident Summary

Incident: 3592 **Date/Time Notice:** 12/29/2014 **DEM Incident No:** 3547

Responsible Party: Eiker Inc

Date Incident: 11/28/2014 **Time Incident:** 11:30 am **Duration:**

County: McKenzie **Twp:** 148 **Rng:** 105 **Sec:** 26 **Qtr:**

Lat: 47.60838 **Long:** -104.01390 **Method:** Interpolation from map

Location Description: East side of the road.

Submitted By: Marlene Eiker

Affiliation:

Address: 557 Road 261

City: Glendive

State: MT

Zip: 59330

Received By:

Contact Person: Paul Eiker
557 Road 261
Glendive, MT 59330

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: Vehicle Accident

Description of Released Contaminant: Production Water

Volume Spilled: 15.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Icy roads

Risk Evaluation:

none

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Snow/soil in ditch

Action Taken or Planned:

Absorbent material used to absorb spill.

Wastes Disposal Location:

Agencies Involved: Local Law Enforcement

Updates

Date: 12/29/2014 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Updated Volume:

Notes:

Release due to vehicle accident; some of vehicle's load leaked into road ditch. Followup is necessary. Late submission date due to responsible party waiting on sheriff's report before submitting spill report. NDDoH notified of incident via emergency phone on 11/28/2014 at 2:50 p.m.

Date: 3/17/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 3/17/15.

No sign of spill at described location.

No followup is necessary.